



ROHINI

COLLEGE OF ENGINEERING AND TECHNOLOGY


Approved by AICTE and affiliated to Anna University,(An ISO Certified Institution)

Accredited by NAAC with A+ Grade

DEPARTMENT OF MECHANICAL ENGINEERING

24ME403 - METROLOGY & MEASUREMENTS

Dr. A. ARUL MARCEL MOSHI,
ASSOCIATE PROFESSOR / MECH.



24ME403 – METROLOGY & MEASUREMENTS

UNIT I: BASICS OF METROLOGY

CO1: To explain the basics of standards of measurement and errors in industrial applications.

Terminologies used in Measurement

1. **Range:** Range is the minimum and maximum value of a quantity for which an instrument is designed measure.

Example: For a 15 cm scale, the range of measurement: 0 to 15 cm.



2. **Span:** Span is the difference between the maximum and minimum value of the measurement range.


Example: For a 15 cm scale, the span is $15 - 0 = 15$ cm.



3. **Error:** The difference between the true value (exact value) and the obtained value is called as 'Error'.

$$\text{Error} = \text{Measured value} - \text{True value}$$


Example: a temperature measurement has its measured value as 34°C , and the true value as 35°C , the error is $35 - 34 = 1^{\circ}\text{C}$.



4. **Accuracy:** Accuracy is how close a measured value is to the true or accepted value of the quantity being measured.
5. **Precision:** Precision is the degree of closeness among repeated measurements of the same quantity.

Precision indicates the consistency or reproducibility of a measurement process, not how close they are to the true value.

Accuracy vs Precision (Example): Hitting a target, accuracy means your shots are close to the bullseye, while precision means your shots are clustered tightly together, even if they're away from the centre.




6. **Sensitivity:** Sensitivity is the smallest change in the measured quantity that the instrument can detect and display as a change in the reading.

Example: A thermometer with high sensitivity can detect a temperature change as small as 0.01°C .



7. **Stability:** Stability refers to the ability of an instrument to give consistent and repeatable readings over time when measuring the same quantity under the same conditions.

Example: A digital weighing scale that shows the same 50.0 kg reading for an object when measured repeatedly over several months demonstrates excellent stability.



8. **Threshold:** Threshold is the minimum value below which no output change can be detected when the input of an instrument is increased gradually from zero.

Example: A pressure sensor with a 0.5 Pa threshold will not register any output change until the applied pressure exceeds 0.5 Pa.

9. **Calibration:** In measurement, calibration means comparing a measuring instrument with a known, accurate standard to check its readings and adjust it if needed, so that it measures correctly.


Example: Calibrating a laboratory balance involves comparing its readings against a set of certified standard weights to ensure accurate measurement.



10. **Tolerance:** Tolerance means the allowable amount of variation in a measurement or dimension without causing problems.

It is the maximum allowable error in the measurement.

Example: A machined shaft with a specified diameter of $25.00 \text{ mm} \pm 0.05 \text{ mm}$ has a tolerance of 0.10 mm , meaning any measurement between 24.95 mm and 25.05 mm is acceptable.



11. **Drift:** Drift is the variation of change in output for a given input over a period of time.

Example: A temperature sensor that reads 22.0°C at the start of a test but slowly increases to 22.8°C over eight hours without any change in the actual temperature is exhibiting drift.

12. **Zero Drift:** Zero drift is the change which occurs in the output when there is zero input is given.

Example: A digital micrometer that reads $+0.005 \text{ mm}$ when its measuring faces are fully closed and in contact (zero condition) is exhibiting zero drift, requiring recalibration before use.

13. **Uncertainty:** In measurement, uncertainty means the doubt or range of possible error in any measurement.

It tells you how much you can trust a measurement.

Example: When measuring a steel block's length with a caliper, the reported value is $50.25 \text{ mm} \pm 0.02 \text{ mm}$, where $\pm 0.02 \text{ mm}$ represents the measurement uncertainty.

14. **Response time:** Response time is the time an instrument takes to show a correct, stable reading after a change in the quantity being measured.

Example: A thermocouple installed in an engine exhaust has a response time of 200 milliseconds.

15. **Repeatability & Reproducibility:** Repeatability is measurement consistency by the same person, same equipment, same conditions; reproducibility is consistency across different people, different labs, or different equipment (broader reliability).

Repeatability shows immediate precision and operator skill, while reproducibility validates a method's universal applicability, ensuring results aren't just a fluke of one specific setup, crucial for scientific trust.



Repeatability vs Reproducibility (Example): Repeatability is when the same operator uses the same micrometer on the same shaft ten times and gets nearly identical results; reproducibility is when three different operators in three different labs measure the same shaft with different micrometers and all arrive at the same result within an acceptable range.