

2.4 No load current

The phasor sum of the magnetizing current (I_m) and the loss component of current (I_c); I_m is calculated using the MMF/m required for the core and yoke and their respective length of flux path. I_c is determined using the iron loss curve of the material used for the core and yoke and the flux density employed and their weight.

The no-load current I_0 is the vectorial sum of the magnetizing current I_m and core loss or working component current I_c . [Function of I_m is to produce flux ϕ_m in the magnetic circuit and the function of I_c is to satisfy the no load losses of the transformer].

Thus, No load input to the transformer = $V_1 I_0 \cos \phi_0 = V_1 I_c =$ No load losses as the output is zero and input = output + losses.

Since the copper loss under no load condition is almost negligible, the no load losses can entirely be taken as due to core loss only. Thus the core loss component of the no load current




Figure 2.5.1 Transformer under no-load condition Vector diagram of Transformer under no-load condition

[Source: "A Course in Electrical Machine Design" by A.K.Sawhney, page-5.98]